RESON 7125 SV Complete



All Serial Connection to computer
need Null Modem Cable
2,3,5 going to 3,2,5

POS-MV





The MRU was used as the RP



HYPACK





Check Carefully to insure the coordinate system used by the software is correct